

# High Alloy Steels and Schöffler Diagram

Illustration

I have introduced Schöffler diagrams *schematically* in "[The science of alloying](#)". **Anton L. Schöffler** published the first one in 1949; W.T **De-Long** improved on it in 1974; that's why it is sometime called the Schöffler - De Long diagram. Here is a "real" one with a lot of information about real steels drawn in:

